

AIRS/AMSU/Aqua Operations Update

Denis Elliott

April 24, 2012

Copyright 2012
California Institute of Technology
Government sponsorship acknowledged

AIRS/AMSU/Aqua Operations Update AIRS Science Team Meeting April 24–26 2012 Pasadena CA



Outline

- AIRS operations status
- AMSU-A operations status
- Aqua spacecraft status
- AMSR-E spin-up plans
- New AIRS gain table



AIRS Operations Status




AIRS Operational Status

- AIRS is in excellent health
- All engineering parameter plots versus time are either flat or changing extremely slowly—no concerns
- Some channels have degraded noise performance due to radiation dosage
 - Many of the degraded channels have recently had their noise performance significantly improved by revising the on-board gain table
 - Details later in this presentation




AIRS Chopper Drive Current






AIRS Scan Mirror Temperature






AIRS Choke Point Heater Current






AIRS Cooler A Drive Level






AIRS Cooler B Drive Level





AIRS Focal Plane Temperature







AMSU-A Status



AMSU-A Operational Status

- AMSU-A mechanical parts and most of the electronics are in good health
- Engineering parameter trends are slow—no concerns
- 10 of the 15 channels are healthy, but
 - Channel 4 failed in 2007 (declared non-operational on October 1 2007)
 - Channel 5 is now too noisy to contribute to Level 2
 - Channel 7 noise has exceeded specs since launch and has never been used for L2
 - Channel 6 has been degrading slowly since 2008
 - Channel 1 recently began degrading




AMSU-A1-2 RF Shelf Temperature

April 24-26 2012 Pasadena CA


Atmospheric Infrared Sounder

Government sponsorship acknowledged






AMSU-A2 RF Shelf Temperature






AMSU-A1-2 Noisy Bus Current





AMSU-A Channel 5 ΝΕΔΤ

Atmospheric Infrared Sounder




Copyright 2012
California Institute of Technology
Government sponsorship acknowledged

AIRS/AMSU/Aqua Operations Update AIRS Science Team Meeting April 24–26 2012 Pasadena CA

16




AMSU-A Channel 6 ΝΕΔΤ





AMSU-A Channel 1 ΝΕΔΤ





Aqua Status And And Anomalies



Aqua Spacecraft Health Status

- Aqua is in very good health
- Several anomalies have occurred over the years
- All are considered minor
- None have yet impacted operations




Aqua Fuel Supply

- Occasional drag make up burns use only a very small amount of fuel
- Most fuel usage takes place in orbital inclination adjustment maneuvers, needed to keep Aqua properly aligned with other A-train instruments and to tightly control our 1:30 pm crossing time
 - Three or four such maneuvers are planned every year, near the vernal equinox
 - A recent estimate of future fuel usage indicates that the hydrazine should last at least until 2022, and possibly longer



Projected Aqua Fuel Usage





AMSR-E Spin-up Plans



AMSR-E Anomaly Background

- Suffered numerous anomalies (excess commanded torque and excess current in scanner) over the past several years
- On October 4 2011, in response to the largest of these anomalies yet seen, the instrument was commanded to slow from 40 rpm to 4 rpm
- When problems continued even at 4 rpm the antenna was parked
- Lubricant failure is probable cause
- Spacecraft jitter was seen in AIRS geolocation data during the spin down, but there was no noticeable impact to science on AIRS or any of the other instruments



AMSR-E Spin-Up

- Not yet declared dead
- AMSR-E team is requesting a spin-up to 4 rpm to enable cross-calibration with a new instrument, AMSR2, being launched on GCOM-W1 on May 18
- Earth Science Mission Operations (ESMO) project at GSFC, responsible for Aqua operations, is proposing spinning up to just 2 rpm, at least at first
- Planning for the spin-up and negotiations with JAXA are in progress
- No action likely before August



New AIRS Gain Table




Rationale For a New Gain Table

- A new detector gain table was tested on October 9 for 24 hours
- It changed the gains for 172 channels and was extremely successful as far as noise performance is concerned
- Worries about its possible impact on climate studies led to a second table that changed only 107 channels
- That table went operational on January 21



Channel 476 (801.5 cm⁻¹) $A+B \rightarrow A$

Atmospheric Infrared Sounder




B side suffered radiation hit on 9/30/2009

Copyright 2012 **California Institute of Technology** Government sponsorship acknowledged **AIRS/AMSU/Aqua Operations Update AIRS Science Team Meeting** April 24-26 2012 Pasadena CA



Channel 758 (900.0 cm⁻¹) A+B -> B

Atmospheric Infrared Sounder




A-side suffered radiation hit in late 2004

Copyright 2012 **California Institute of Technology** Government sponsorship acknowledged AIRS/AMSU/Aqua Operations Update **AIRS Science Team Meeting** April 24-26 2012 Pasadena CA



Channel 2357 (2642.2 cm⁻¹) $A+B \rightarrow A$

Atmospheric Infrared Sounder



Channel looked good in A+B state immediately after the shutdown in late 2003

Almost immediately, steady deterioration set in

The problem was the B detector

Copyright 2012 **California Institute of Technology** Government sponsorship acknowledged **AIRS/AMSU/Agua Operations Update AIRS Science Team Meeting** April 24-26 2012 Pasadena CA